







Commercial Refrigeration (Supermarkets) Title 24 Standards

Leak Reduction Measures (Design and Installation)

Proposed 12/16/10



ICF International California Energy Commission Heschong Mahone Group, Inc. VaCom











Leak Reduction Measures

- Measures aimed at ensuring "base practices" for minimizing leakage at system design & installation
 - Intended to set "floor," not "ceiling"
- Measures are cost-effective & reflective of basic good practice
- Sources used to develop measures:
 - American National Standards Institute (ANSI) standards
 - American Society of Heating, Refrigerating, and Air-Conditioning (ASHRAE) standards
 - The International Mechanical Code (IMC)
 - Stakeholder input (equipment manufacturers, contractors, users)













- Twelve draft proposed measures*
 - #1-3 related to piping
 - #4-6 related to valves
 - #7–12 related to other installation practices

*Since September, some measures have been deleted, combined, and/or revised based on additional research and stakeholder input











 Piping runs using threaded pipe must not be used for refrigeration lines (e.g., if steel piping is used, it must be welded). This does not include the control connections at the compressor.

Benefits

 Threaded joints can seep refrigerant; welded piping is more durable, less prone to leakage over long-run

Cost

 Minimal; costs of welded/brazed vs. threaded pipe depends on pipe size & skill set of installers













 Use of copper tubing with an outside diameter (OD) smaller than ¼" is prohibited in all but systems with a refrigerant charge of 5 lbs or less. When using ¼" tubing, it must be clamped to a rigid base every 2 feet.

Benefits

Prone to failure when subject to severe vibration

Cost

 ~\$30/system for additional labor; will depend on store size













- Flare fittings prohibited from use on all refrigerant applications with the exception of pressure controls, valve pilot lines, and oil lines.
- In these exception cases, pressure controls and valve pilot lines must use double-flare connections.

Benefits

- Flare fittings are more leak-prone than brazed/threaded fittings
- Flare fittings on expansion valves more difficult to access for leak checking

Cost

• Minimal; flare fittings may be easier (i.e., faster, cheaper) to service













• Pressure relief valves must be equipped with a device to indicate a release of refrigerant (e.g., manufacturer-installed diaphragm with a visual indicator).

Benefits

 Service technicians can more easily identify valves that have discharged so that they may be checked for possible refrigerant seepage

Cost

 Rupture disc relief valve with a gauge ~\$140/pressure relief valve













- Only Schrader access valves with a brass body are permitted for use.
- For systems with ≥ 5 lbs refrigerant, valve caps on Schrader access valves shall be brass (not plastic); a neoprene O-ring seal must be in place, if designed for it.

Benefits

Prohibits the use of valves that are more prone to leakage

Cost

<\$15-\$20/valve (for brass vs. plastic caps)</p>













• Valves not having an internal stem diaphragm must have seal caps with chain tethers to fit over the stem.

Benefits

- Ensures caps are installed with the proper O-ring seal in place
- Caps less likely to be lost or misplaced with chained tethering

Cost

<\$15-\$20/valve (will depend on size of valve)



12/16/2010











 Evaporator coils in deli cases must be coated to prevent corrosion from vinegar and salt solutions in the displayed product.

Benefits

 Protecting coils in deli cases reduces corrosion, which can lead to leakage

Cost

 ~\$300- \$700/coil for coating (will depend on size of coils, type of coating, and manufacturer/service provider)













• Piping and components shall be installed in such a manner as to protect the piping and components from physical damage.

Benefits

 Poorly placed components are more susceptible to breakage & leakage

Cost

 Expected to be negligible; measure can easily be addressed in design process













• Refrigerant piping shall be installed in such a way so that it is accessible for leak detection and repairs.

Benefits

 Piping that can't easily be leak checked or replaced is more susceptible to undetected and prolonged leaks

Cost

 Will vary on a store by store basis; measure can be addressed in design process













• Install receiver level sensors on receivers with 200 pounds or more of refrigerant.

Benefits

 Can be used to detect leaks that may not otherwise be easily detected

Cost

Cost estimates being developed



12/16/2010











- Pressure test system during installation prior to evacuation & charging:
 - Charge the system with regulated dry nitrogen and the appropriate tracer gas to bring system pressure up to 300 psig minimum.
 - After the system has been checked for leaks and all leaks have been repaired and retested, the system must stand, unaltered, for 24 hours with no more than a +/- 1 pound pressure change from 300 psig, using the same gauge.

Benefits

 Holding the system at a high pressure for 24 hours will pick up even small leaks, thus ensuring leak tightness of equipment at installation

Cost

 Associated with evacuation & isolation procedures, which could result in additional labor time & delay in the store opening













- Evacuate system following pressure testing & prior to charging:
 - Pull a system vacuum down to at least 1000 microns (+/- 50 microns) and hold for 30 minutes.
 - Pull a second vacuum to a minimum of 500 microns and hold for 30 minutes.
 - Pull a third vacuum to a minimum of 300 microns and hold for 24 hours with a maximum drift of 100 microns over the 24-hour period.

Benefits

 Pulling system vacuum three times will validate leak tightness while ensuring that the system is free of impurities prior to charging

Cost

 Associated with evacuation & isolation procedures, which could result in additional labor time & delay in the store opening











Contact Information

Comments on proposed measures can be provided to:

CEC: Martha Brook

(916) 654 - 4086

Mbrook@energy.state.ca.us

or

ARB: Glenn Gallagher

(916) 327-8041

ggallagh@arb.ca.gov

For more background on measures visit: http://www.h-m-g.com/T24/CASE.htm